



FIBRWRAP®

Worldwide Specialized Contractors

Strengthening Structures | Protecting Lives Worldwide.



Transportation



Buildings




Pipelines



Waterfront



Industry



Pipe strengthening of SDCWA Fallbrook, Fallbrook, USA.

Three 96" diameter PCCP sections at the San Diego County Water Authority were deemed structurally deficient due to corrosion. Fibrwrap® Construction was contracted to provide the required repair.

The Tyfo® Fibrwrap® System was designed to resist the loads from the earth's pressure, live loads, and internal pressures. 1 layer of the carbon-based Tyfo® SCH-41-2X System was installed in the longitudinal direction and 8 layers in the hoop direction to restore the pipe back to working capacity.

Fibrwrap® Construction was able to mobilize quickly and perform the repair in an effective and timely manner, resulting in time savings and shut down time.



Project: Pipe strengthening of SDCWA Fallbrook

Location: Fallbrook, USA

Client: San Diego Water Authority

Scope of Works:

- Structural Repair of three 96-inch diam. PCCP



www.fibrwrapgroup.com

www.fibrwrapconstruction.com